

2. Concern: No A/C source on 10" touch screen

Cause: Bad RV-C bridge to module and amp rings or donuts

Correction: Replace amp rings or donuts and RV-C bridge per Spyder controls rep. Talked to Michael at Pleasure Way and he referred tech to Spyder controls who trouble shot over phone

Time: 2 hrs 2.0 approved maximum.