

SSM 49694: 2020-2021 F-53 Motorhome Chassis - Rear Stabilizer Bar Service

Some 2020-2021 F-53 Motorhome Chassis vehicles requiring service to the rear stabilizer bar may have a detached weld nut on the rear axle housing. Service this missing nut with part number W713546-S439.

Vehicles:

2020-2021 F-53 Motorhome Chassis | F-59 Commercial Stripped Chassis (Y3)