

From: [Polaris Service](#)
To:
Subject: Test Team Tip I-21-03-01 Released
Date: Thursday, March 25, 2021 1:51:23 PM

I-21-03-01 | [Trouble viewing this email?](#)



Date: March 25, 2021
Attn: Indian Motorcycle Service Department
Subject: Team Tip I-21-03-01 Released

Questions: Contact Indian Motorcycle Technical Service

Dear Indian Motorcycle Dealer,

Please review the following communication that was posted Thursday, 03/25/2021.

Indian Motorcycle has identified some erroneous faults that may appear on 2022 Indian Chief models during specific events, such as cold starts with low battery voltage.

Click [HERE](#) to view Team Tip I-21-03-01

Thank you for your attention.

Sincerely,

Indian Motorcycle Service

This email was sent by Polaris Inc to

[Privacy Policy](#)

© 2021 Polaris Inc
2100 Highway 55, Medina, MN 55340, USA | [Polaris.com](#)