

WMC9 Stop Delivery - Reworking screw connections of shock absorbers on front and rear...

Version 1

WMC9 Stop Delivery - Reworking screw connections of shock absorbers on front axle and rear axle

IMPORTANT REMINDER

IT IS A VIOLATION OF FEDERAL LAW FOR DEALERS TO DELIVER TO CUSTOMERS NEW VEHICLES IN THEIR INVENTORY AFFECTED BY THIS NOTIFICATION UNTIL THESE VEHICLES ARE REMEDIED. DEALERS SHOULD NOT SELL, LEASE, RENT, OR LOAN ANY NEW OR USED VEHICLES IN DEALER INVENTORY AFFECTED BY THIS

NOTIFICATION PRIOR TO REMEDY. DEALERS GROUNDING LEASE RETURNS SHOULD REMEDY ALL AFFECTED GROUNDED VEHICLES.

Overview

On some of the affected vehicles, there is a possibility that individual screw connections of the shock absorbers on the front axle and rear axle may not have been tightened to specification. As a result, the durability of the respective screw connections cannot be assured.

The affected fastening screws must be replaced and tightened according to the original specification. On certain specific vehicles where the front axle is affected, the spring-strut mounts must also be replaced.

Model type	Macan (95B)
Model year	2021
Number of affected vehicles	7

Vehicle usage

The vehicles may only be driven for loading and unloading purposes in the transport chain. Further use is not permitted. Test drives are to be omitted.

Test instructions and remedial measures

Will be communicated once available (approx. cw 14).

[WMC9 Stop Delivery VIN List.XLSX](#) ⓘ

8.8 KB

(194 views)

Created by [Ryan Cooney](#) on Mar 23, 2021 7:00 PM. Last modified by [Ryan Cooney](#) on Mar 23, 2021 7:04 PM.

Categories: Macan, Stop Sale

Tags : [stop delivery](#), [95b ii](#), [my m](#), [wmc9](#)

821 Views [Report Abuse](#)

Content and Topics

Personal

Manage

Create

- Your Groups >
- Your Content >
- Your Places >
- Edit Profile >
- Change Password >
- Admin Console >
- PPN Administration >
- Discussion >
- Files >
- Document >
- Collaboration >
- Document
 - Blog Post >
 - Poll >
 - Event >
 - Photo Album >
 - Idea >
 - Space >
 - Group >

© 2021 Dr. Ing. h.c. F. Porsche AG. Legal notice. Copyright. Terms of use. Privacy Policy. Cookie Policy. [010](#)