

CAMPAIGN LAUNCH STATUS

N534 SERVICE ACTION - 21MY RR VELAR AUTO ACCESS HEIGHT



SERVICE ACTION N534- CCF UPDATE- AUTO ACCESS HEIGHT FEATURE

AFFECTED MODELS

21MY Range Rover Velar

VOLUME AFFECTED

364 USA 42 CAN

REPAIR

Affected vehicles do not have the auto access height option available in the vehicle convenience settings menu. A new car configuration file (CCF) is required using Pathfinder to correct this

REPAIR TIME

0.2 hrs + Drive in/out

CAMPAIGN LAUNCH

February 16th, 2021

Notes

Vehicles in retailer inventory must be updated prior to sale. Sold cars are to be repaired at the next service visit.



PRINTED COPIES ARE UNCONTROLLED