

## TECHNICAL TOPICS

### BODY/CHASSIS



#### Air Conditioning Operation

16 - 21MY Range Rover, RR Sport

#### Customer Voice:


- A customer may report the air conditioning system is not cooling properly.

#### Technical Description:

- This may be caused by a vehicle that is in a low state of refrigerant charge or compressor control solenoid fault.
- A/C compressor have been replaced and return of the compressors for analysis has found no fault with the compressor unit.

#### Status:

- Guided Diagnostics has been updated and symptom driven pinpoint tests are available to aid in properly diagnosing HVAC system performance concerns and should be followed to ensure a correct first time diagnosis/ repair is made.
- If Guided Diagnostics does not lead you to the root cause of the concern, please submit a TA case so diagnostic support can be provided.



4100310  
08-2018  
30  
00275644-03  
© Copyright 2017 - 2018 Jaguar Land Rover Limited.

