

TECHNICAL TOPICS

BODY/CHASSIS



Deployable Side Steps Not Operating

21MY Discovery

Customer Voice:

- A customer may report that the deployable side steps are inoperative.

Technical Description:

- The Deployable Side Steps (DSS) module may have gone offline as the vehicle CAN bus network awakes.

Status:

- **SSM 75305** is being published to provide repair guidance to correct this concern.
- Should a customer express a concern, please refer to this SSM for repair guidance.

