

TECHNICAL TOPICS

BODY/CHASSIS



Air Conditioning Operation	16 - 21MY Range Rover, RR Sport
<p><u>Customer Voice:</u></p> <ul style="list-style-type: none"> - A customer may report the air conditioning system is not cooling properly. <p><u>Technical Description:</u></p> <ul style="list-style-type: none"> - This may be caused by a vehicle that is in a low state of refrigerant charge or compressor control solenoid fault. - A/C compressor have been replaced and return of the compressors for analysis has found no fault with the compressor unit. <p><u>Status:</u></p> <ul style="list-style-type: none"> - Guided Diagnostics has been updated and symptom driven pinpoint tests are available on TOPIx> Workshop Manual> Section 412-00> Diagnosis and Testing to aid in properly diagnosing HVAC system performance concerns and should be followed to ensure a correct first time diagnosis/ repair is made. - If further support is required, please submit a TA case so diagnostic support can be provided. 	<p>4120310 08-2018 38 00275844-03</p> <p>© Copyright 2017 - 2018 Jaguar Land Rover Limited.</p>

