

Classification:

BT21-005

Reference:

ITB21-004

 COPYRIGHT© NISSAN NORTH AMERICA, INC.
 Date:

March 15, 2021

2020 QX50; WINDSHIELD REPLACEMENT

APPLIED VEHICLE: 2020 QX50 (J55)

SERVICE INFORMATION

Three additional windshield part numbers were added to the Electronic Parts Catalog (EPC) for the 2020 QX50. If the windshield on an applied vehicle needs to be replaced for any reason, enter the VIN into the EPC to obtain the correct part number.

AMENDMENT HISTORY

PUBLISHED DATE	REFERENCE	DESCRIPTION
March 15, 2021	ITB21-004	Original bulletin published

Infiniti Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. **NOTE:** If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Infiniti retailer to determine if this applies to your vehicle.