



## STAR ONLINE PUBLICATION



**Case Number:** S2121000001

**Release Date:** 03/04/2021

**Symptom/Vehicle Issue:** CV Boot Leak Inspection, Boot Inspection

**Discussion:** As part of launch awareness and quality assurance, the outer CV boot areas should be inspected for signs of contact damage as highlighted. Use the attached photos as a reference guide while examining the outer CV boots. If there are contact marks like the highlighted, replace the "**front halfshaft**" as needed.



This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

**Contact STAR Center, or your Technical Assistance Center Via TechCONNECT or eCONTACT ticket if no solution is found**