

2020 Ontour

C/S THEY ARE NOT GETTING ANY HEAT OR HOT WATER AND SMELL GAS.C) TRUMA TOUCH PAD DISCONNECTED .WATER HEATER SWITCH TURNED OFF AND LP SHUT OFF.R) RECONNECTED AND TURNED ALL ON WATER HEATER AND FURNACE WORK. FOUND LP REGULATOR LEAKING. R&R TWO STAGE REGULATOR. TIME 0.70 HRS

0.50 approved.