

## Suspension fault message "drive at max 80 km/h" in instrument cluster

---

Topic number	LI32.34-P-072600
Version	1
Function group	32.34 - Anti roll governor (WR)
Date	3/9/21
Validity	167.xxx with code 465
Reason for change	

---

### Complaint

Suspension fault message in instrument cluster to drive at max. 80 km/h

### Cause

Software for torsion bar control unit, front and/or rear (A108/2 and/or A108/3)

### Remedy

Update software via XENTRY, version 12/2020 or later

<b>Symptoms</b>
Chassis/suspension > Suspension/Dampening > Roll control > Malfunction

<b>Control unit/fault code</b>	
Control unit	Fault text
A108/2 - Active roll stabilization FRONT (Roll control)	
A108/2 - Active roll stabilization FRONT (Roll control)	
A108/3 - Active roll stabilization REAR (Roll control)	
A108/3 - Active roll stabilization REAR (Roll control)	

<b>Operation numbers/damage codes</b>				
Op. no.	Operation text	Time	Damage code	Note