



Adam_Mechanic

New User

02-05-2021 07:10 AM

ABS 11 SPN 807

14 Cascadia FJ1682, has ABS11 SPN807 on dash, anything i can find online says it has to do with the Dif 2 ASR Valve. Ive checked this valve out, have even replaced it, (those O-rings are a pain btw to keep in place) and have sprayed a water/soap solution around it to make sure there is no air leaking from it. The wheel speed sensors voltages and resistances check out within normal spec. We had it into Freightliner once before and they said it was a fuse, ive checked every possible fuse on this thing and relay and nothing it blown or damaged and i cant get them to tell me exactly which "fuse" was bad. Where do i go from here?

Labels :

Brakes | Air | and Hydraulic Systems

Cascadia

Electronics | Controls | Configuration | Communication | and Diagnostics

Freightliner

Power | Electrical | Harnesses | and Wiring

Add tags



0 Kudos

Reply



Ryan_Picken

Knuckle Buster

04-26-2021 10:17 AM

SPN 807 has more than 10 FMI's each one with its own fault description as to how the circuit/device is failed. If you add the FMI then we can assist.

Add tags



0 Kudos

Reply

