

TECHNICAL TOPICS BODY/CHASSIS



<p>Customer Voice:</p> <ul style="list-style-type: none"> - A customer may report the air conditioning system is not cooling properly. <p>Technical Description:</p> <ul style="list-style-type: none"> - This may be caused by a vehicle that is in a low state of refrigerant charge or compressor control solenoid fault. - A/C compressor have been replaced and return of the compressors for analysis has found no fault with the compressor unit. <p>Status:</p> <ul style="list-style-type: none"> - Guided Diagnostics has been updated and symptom driven pinpoint tests are available on TOPIX> Workshop Manual> Section 412-00> Diagnosis and Testing to aid in properly diagnosing HVAC system performance concerns and should be followed to ensure a correct first time diagnosis/ repair is made. - If further support is required, please submit a TA case so diagnostic support can be provided. 	<p>16 - 21MY Range Rover, RR Sport</p>

