



Chassis Advisory Notice – Short circuit at battery terminal

Jayco - Body Builder	
Bulletin Type:	<u>Chassis Advisory Notice</u>
Jayco CAN #:	21-012
Publication Date:	05/07/2021
Make:	Jayco
Model(s):	Redhawk SE
Model Year:	2021 and 2022

Chevy– Chassis Builder	
Chassis Bulletin:	Safety Recall
Chassis SA #:	21V189
Publication Date:	April 2021
Chassis Model:	Express 4500
Chassis Model Yr:	2021
Component/Area:	Battery cable terminal

Chassis Incident:	<p>Anti-rotation tabs on the positive battery cable terminals may come into contact with a fuse block assembly attachment post, causing a short circuit. Clearance between the positive battery cable anti-rotation tab and the fuse attachment posts is small enough to allow contact in certain situations. Drivers may get a low battery voltage warning or experience a dead battery. A short-circuit of a positive battery cable to a fuse attachment post can cause battery drain or may lead to an underhood fire.</p>
WARNING :	<p>It is recommended that the vehicle be parked outside and not in a garage or other structure until it is repaired.</p>
Chevy Customer Assistance	1-800-833-2438