

2021 Ontour

1) Passenger side rear window is leaking when it's raining.

Correction: pulled pass side window out of the coach

Removed butyl tape and gasket from the coach and the window frame

Installed new gasket on the back of the window frame

Reinstalled the window into the coach

Set up sprinkler to water test the window for 45 minutes. No leaks inside the window.

Time: 2.5 hours + gasket part cost \$15.60 approved.