




## Mack Chassis - Hood Mirror Vibration - Model AN



> Internal Content

A product improvement has been made to the Mack Anthem Hood Mirror. The supplier has reinforced the mirror glass carrier backing to make it more robust by filling in the tabs as seen below. The component material has changed from ASA to ABS plastic. This improvement affects Mack Anthem trucks, built from January 1, 2018 thru May 24, 2021.



**NOTE:** All mirror glass carrier assemblies are manufactured as heated. If the truck does not have the heated mirror option, simply ignore the electrical contacts. See the electrical contacts in the illustration below.



For more information refer to **TPI 846-016** located in Impact.

<b>Previous Assembly</b>	
<b>P/N</b>	<b>Description</b>
78620286	LH Unheated Assembly
78620287	LH Heated Assembly
78620288	RH Unheated Assembly
78620291	RH Heated Assembly

<b>Updated Assembly</b>	
<b>P/N</b>	<b>Description</b>
78620290	RH Heated Assembly
78620285	LH Heated Assembly



Tags

[mirror rattle](#)

[mirror shake](#)

[mirror vibration](#)

### Related links and attachments

No links or attachments available



### Feedback

[Give feedback](#)

to help improve the content of this article