



Bulletin No.: PIC6435A  
Published date: 05/7/2021

# Preliminary Information

## PIC6435A Service Adaptive Headlamp Message, Lin Bus DTC U1523 Setting After Right Headlamp Replaced

### Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Cadillac	XTS	2013 - 2014	All	All	All	All

Involved Region or Country	North America
Condition	Service Adaptive Headlamp message with DTC U1523 setting after right headlamp replacement.
Cause	Part Issue

### Correction:

Engineering is aware of the concern and is investigating the issue. This PI will be updated when a resolution is available.

### Version History

Version	2
Modified	03/31/2021 - Created on. 05/07/2021 - Updated Model Years and Correction.



GENERAL MOTORS

© 2021 General Motors. All Rights Reserved.