

DTNA Solutions > Service Solutions > Thomas Built Bus
> SS 284 TBB 2021 DD5 low dash heat

SS 284 TBB 2021 DD5 low dash heat

This Service Solution does not imply any special warranty coverage. Standard warranty guidelines and coverage applies. This Service Solution is provided to assist Dealers/Customers in resolving the issue of Low heat in the dash or body heaters.

Applicable Vehicles

C2 with DD5 Engine

Symptoms

Lack and or low heat in the drivers area

Issue

Unknown, as Detroit is looking into the matter. if you have this concern you can add a Flow Restrictor TBB 66000366 in the return line at the manifold tubing. Refer to diagram D22-75463, page 2 item 31

SRT .2

Below component and the VRMS code

VMRS Code for PN: TBB 66000366 FLOW RESTRICTOR - HEATER, 5/16 X 1.00"

174-026-029 FITTING - BUS BODY HEATER

Solution

Shut the return line valve off, and the line connecting to the manifold pipe you can pinch the line off with an smooth type clamp. Loosen the clamp, remove the hose, and insert the Restrictor.

Labels :

Saf-T-Liner

Add tags


Attachments




1 Kudo


Comment



-000 SHOWN



-001 SHOWN







DETAIL - B
-000 & -001

1 8 13

INFORMATION CONTAINED HEREIN IS PROPRIETARY DATA, AND IS NOT FOR DISSEMINATION OR DISCLOSURE, IN WHOLE OR IN PART, FOR ANY PURPOSE OTHER THAN THAT FOR WHICH IT WAS SUBMITTED. FOR INFORMATION ON THIS POLICY, SEE THE DAIMLER GROUP INTELLECTUAL PROPERTY POLICY.


DAIMLER

Daimler Trucks
North America


ITEM/DRAWING NUMBER
D33 75163

REVISION LETTER


PAGE
2 of 3




DETAIL - C
-000 SHOWN



DETAIL - H
-001 SHOWN



VIEW - K
-000 & -001



VIEW - K



VIEW - D
-000 & -001

9 12 17

2 PLACES

ENG CAC BRKT

