

CAMPAIGN LAUNCH STATUS

H348 AND N572 - SERVICE ACTION - E-SUPERCHARGER



OWNER NOTIFIED SERVICE ACTIONS H348 AND N572

AFFECTED MODELS	21MY F-PACE 21-22MY RR/RRS/EVOQUE/DISCOVERY/VELAR/DEFENDER WITH P6 ENGINE
VOLUME AFFECTED	676 USA 106 CAN
REPAIR	Certain models within the affected model and VIN ranges may have been built with superchargers with an internal circuit board that could short circuit leading to a MIL and reduced engine performance. All affected vehicles will require a replacement e-supercharger
REPAIR TIME	Between 1.6 and 2.7 hrs dependent on model + DIDO
TARGET CAMPAIGN LAUNCH	June 10 th 2021
Notes	c. 83 units are in Retailer Inventory



PRINTED COPIES ARE UNCONTROLLED