

<h2>Heated Steering Wheel Performance</h2>	<h2>19MY – Onwards Range Rover, RR Sport</h2>
<p><u>Customer Voice:</u></p> <ul style="list-style-type: none">- A customer may report that the steering wheel heater is not hot. <p><u>Technical Description:</u></p> <ul style="list-style-type: none">- This may be caused by a number of different potential factors. <p><u>Status:</u></p> <ul style="list-style-type: none">- The guided flow diagnostics has been updated to provide enhanced diagnostics for heated steering wheel concerns.- Please refer to Guided Diagnostics on TOPIX> Workshop Manual> Section 211-04> Diagnosis and Testing> Heated Steering Wheel for aid in properly diagnosing heated steering wheel performance concerns.	
	