

**Reference:**

ITB10-015B

**Date:**

June 16, 2021

## **VOLUNTARY SERVICE CAMPAIGN 2010 G37 WITH NAVI; RADIO SEEK FUNCTION**

**CAMPAIGN ID #:** P0308**APPLIED VEHICLE:** 2010 G37 Sedan, Coupe, & Convertible (V36, CV36, & HV36)

### **Service Campaign ID # P0308 is no longer active.**

- Repair orders opened after this bulletin's published date are no longer eligible for reimbursement under Campaign ID # P0308.
- Discard all previous versions of ITB10-015.

### **AMENDMENT HISTORY**

| <b>PUBLISHED DATE</b> | <b>REFERENCE</b> | <b>DESCRIPTION</b>               |
|-----------------------|------------------|----------------------------------|
| January 24, 2011      | ITB10-015        | Original bulletin published      |
| February 2, 2011      | ITB10-015A       | <b>SERVICE PROCEDURE</b> updated |
| June 16, 2021         | ITB10-015B       | Bulletin no longer active        |