

GLOBAL SAFETY FIELD INVESTIGATIONS
DCS5813
URGENT - DISTRIBUTE IMMEDIATELY

Date: June 2, 2021

Subject: N212336340 - Customer Satisfaction Program
Fender Badge Double Charge

Models: 2020-2021 Chevrolet Camaro
Equipped with Shock and Steel Special Edition (RPO B2E)

To: All General Motors Dealers

General Motors is releasing Customer Satisfaction Program N212336340 today. The total number of U.S. vehicles involved is 11. Please see the attached bulletin for details.

Customer Letter Mailing

The customer letter mailing will begin in the near future.

Global Warranty Management (GWM)

The Required Field Action section on the Investigate Vehicle History (IVH) screen will be updated June 3, 2021 or sooner. A list of involved vehicles is attached to this message. Please hold all warranty transactions until IVH has been updated.

END OF MESSAGE
GLOBAL SAFETY FIELD INVESTIGATIONS

Customer Satisfaction Program

N212336340 Fender Badge Double Charge – USA Only



Release Date: June 2021

Revision: 00

Attention: This program is in effect until June 30, 2023.

Make	Model	Model Year		RPO	Description
		From	To		
Chevrolet	Camaro	2020	2021	B2E	Shock and Steel Special Edition

Involved vehicles are marked “open” on the Investigate Vehicle History screen in GM Global Warranty Management system. This site should always be checked to confirm vehicle involvement prior to beginning any required inspections and/or repairs.

Condition	On certain 2020-2021 model year Chevrolet Camaro vehicles, customers ordered the Shock and Steel Special Edition (RPO B2E) package which contained the chrome fender badge, and option CG3 (free flow black fender badge) as an orderable combination. Customers were charged for both options but only received the chrome badge.
Correction	Dealers will provide the customer with a reimbursement check in the amount of \$145.00.

Parts

No parts are required.

Warranty Information

Labor Operation	Description	Labor Time	Trans. Type	Net Item
9105808	Customer Reimbursement Check Issued	N/A	ZFAT	*

* Submit the dollar amount reimbursed to the Customer in Net/Reimbursement. The amount identified in Net Item is the \$145.00 dealer check issued to a customer. Record the check number in the Invoice Number field. Record the VIN on the check. Submit \$20.00 administrative allowance in Net/Admin Allowance.

Service Procedure

Important: Dealers are to verify these three pieces of information prior to issuing a reimbursement check:

1. Original Owner Letter provided by General Motors.
2. Vehicle registration.
3. Driver's license or state ID - verify that it matches the registration and owner letter.

Issue the customer a reimbursement check in the amount of \$145.00. Record the check number in the Invoice Number field and record the VIN on the check.

Dealer Responsibility

All new, used, GM Certified Used, courtesy transportation vehicles, dealer shuttle vehicles, etc. in dealers' possession and subject to this program must be held and inspected/repared per the service procedure of this bulletin before customers take possession of these vehicles. Involved vehicles must be held and not delivered to customers, dealer-traded, released to auction, used for demonstration, or any other purpose.

All GM Certified Used vehicles currently in the dealers' inventory within the Certified Pre-Owned Inventory System (CPOIS) will be de-certified and must be held and remedied per the service procedure in this bulletin. Upon submitting an accepted/paid warranty transaction in the Global Warranty Management (GWM) system, the vehicle can be re-certified for sale within the CPOIS system, or once again be used in the CTP program.

Dealers are to service all vehicles subject to this program at no charge to customers, regardless of mileage, age of vehicle, or ownership, through June 30, 2023. Customers who have recently purchased vehicles sold from your vehicle inventory, and for which there is no customer information indicated on the involved vehicle listing, are to be contacted by the dealer. Arrangements are to be made to make the required correction according to the instructions contained in this bulletin. A copy of the customer letter is provided in this bulletin for your use in contacting customers. Program follow-up cards should not be used for this purpose, since the customer may not as yet have received the notification letter.

In summary, through June 30, 2023, whenever a vehicle subject to this field action enters your vehicle inventory you must take the steps necessary to ensure the program correction has been made before selling the vehicle. In addition, for vehicles entering your facility for service, you are required to ensure the customer is aware of the open field action and make every reasonable effort to implement the program correction as set forth in this bulletin prior to releasing the vehicle.

Customer Satisfaction Program

N212336340 Fender Badge Double Charge – USA Only



Dealer Reports

For dealers with involved vehicles, a listing has been prepared and will be available through GM GlobalConnect Maxis Field Action Reports or sent directly to export dealers. The Inventory tab of the dealer reports will contain VINs that apply to this field action. This information is intended to assist dealers with the **PROMPT COMPLETION** of these vehicles. The Customer In-Service tab will contain customer names and addresses from Motor Vehicle Registration Records. The use of such motor vehicle registration data for any purpose other than follow-up necessary to complete this field action may be a violation of law in several states.

Customer Notification

General Motors will notify customers of this program on their vehicle (see copy of customer letter included with this bulletin).

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the tools, equipment, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your dealer for information on whether your vehicle may benefit from the information.



**We Support
Voluntary Technician
Certification**

Customer Satisfaction Program

N212336340 Fender Badge Double Charge – USA Only



June 2021

This notice applies to your vehicle, **VIN:** _____

Dear General Motors Customer:

We have learned that on your 2020-2021 model year Chevrolet Camaro, the Shock and Steel Special Edition package which contained the chrome fender badge and free flow black fender badge was ordered, but only the chrome badge was received.

What We Will Do: Your GM dealer will provide you with a reimbursement check in the amount of \$145.00. This reimbursement is available to you until **June 30, 2023**.

What You Should Do: To limit any possible inconvenience, we recommend that you contact your dealer as soon as possible to begin the reimbursement process. Please provide this customer letter, your driver's license or state ID and vehicle registration to the dealer in order to receive your reimbursement check.

If you have any questions or concerns that your dealer is unable to resolve, please contact the appropriate Customer Assistance Center at the number listed below.

Division	Number	Text Telephones (TTY)
Chevrolet	1-800-630-2438	1-800-833-2438
Puerto Rico – English	1-800-496-9992	
Puerto Rico – Español	1-800-496-9993	
Virgin Islands	1-800-496-9994	

We want you to know that we will do our best, throughout your ownership experience, to ensure that your Camaro provides you many miles of enjoyable driving.

Neelie O'Connor
Global Executive Director
Customer Experience Operations

N212336340