



SIB 01 04 19

F48 FUEL TANK VENT/PURGE VALVE: LTD WARRANTY EXTENSION

2021-06-01

This Service Information bulletin (Revision 02) replaces SI B01 04 19 **dated June 2020**.

What's New:

- TeileClearing case submission and prior part replacement approval is no longer required
- Reimbursement mailing address updated

MODEL

E-Series	Model Year	Model Description	Production Dates	Engine
F48	2016	X1 xDrive28i Sports Activity Vehicle	August 14, 2015 to October 28, 2016	B46O PZEV/SULEV

For MY 2016 F48 B46O PZEV/SULEV engine vehicles that are **not registered** in the State of California or a State that has fully adopted the State of California PZEV (SULEV) regulation.

The Model information above is for informational purposes only, and it is not the only deciding factor.

Eligible Vehicles

To determination a vehicle's eligibility and to confirm this coverage applies, always perform a VIN-specific DCSnet Warranty Inquiry first.

To assist you in identifying those vehicles that have this component-specific extended limited warranty coverage, the DCSnet Warranty Vehicle Inquiry has been updated with the VIN and component-specific Vehicle Comment shown below:


Please see [SI B01 04 19](#) (DC 13 90 90 03 00). For this vehicle, the fuel tank vent valve limited warranty for defects in materials or workmanship has been extended to 10 year/120,000 mile as determined from the original in-service date. This coverage is subject to the same vehicle eligibility requirements, limitations, and exclusions that apply to the BMW New Vehicle Limited Warranty for Passenger Cars and Light Trucks. Vehicles that are registered in California or a State that has fully adopted the State of California PZEV (SULEV) emission regulation (Model Year dependent), the standard coverage for this component is 15 years/150,000 miles.

If you have Extended Limited Warranty (ELW) eligibility and/or coverage questions, please contact the Warranty department through IDS by selecting Coverage, Policy, Coding Questions and Mileage Corrections **prior** to performing any repair.

SITUATION

Component-Specific Limited Warranty Extension

	<p>For the eligible vehicles that are not covered under the State of California PZEV (SULEV) emission regulation, BMW of North America, LLC (BMW NA) is extending the limited warranty for the vehicles fuel tank vent (purge) valve (shown) to:</p> <ul style="list-style-type: none"> • 10 years/120,000 miles as determined by the vehicle's original in-service date
--	--



This component-specific limited warranty extension applies to defects in materials or workmanship.

This coverage is subject to the same vehicle eligibility requirements, limitations, and exclusions that apply to the BMW New Vehicle Limited Warranty for Passenger Cars and Light Trucks.

Note: This bulletin is notice of a limited warranty extension. This is NOT a notice of a Recall or Service Action.

There is no immediate repair required unless the vehicle is currently experiencing this problem.

Customer Notification Letter

Even though this is NOT a Recall, BMW NA sent VIN-specific customer notification letters.

CAUSE

The vehicle's malfunction indicator lamp (MIL) lights up, one or more of the following fault codes are entered in the DME fault memory:

- 118001 - mixture control: Mixture too lean;
- 118401 - mixture control: Mixture too lean, large deviation;
- 190F08 - fuel tank ventilation system: malfunction;
- 191C02 - fuel tank ventilation system, 2nd discharge point: malfunction; and/or
- 195014 - differential pressure sensor, tank vent valve, signal: stationary

The fuel tank vent valve may be faulty.

CORRECTION

Follow the instructions in the PROCEDURE section.

PROCEDURE

TeileClearing case submission and their prior part replacement approval applies when this component is replaced.

Replace the fuel tank vent valve as instructed after performing ISTA diagnostics and the related test plans.

Additionally, any repairs to address other stored fuel tank vent valve-related faults which require the replacement of a failed fuel tank vent valve are also covered under the terms of this component's extended time and mileage coverage that is described in this bulletin.

PARTS INFORMATION

Obtain and confirm the part numbers for your specific vehicle by entering the chassis number in either ETK or AIR which takes into account specific equipment and/or options.

Part Number	Description	Quantity
Refer to ETK	Fuel tank breather valve	1

Only order the required **parts in the quantities needed** to address customers' vehicles that have confirmed failures.

- TeileClearing procedures apply when applicable.
- If ETK/EPC item identifies additional part(s) that must also be replaced/installed in-conjunction with performing a covered repair, these required additional items are also covered under the terms of this extended limited warranty.
- Also refer to ETK/EPC and the repair instructions for onetime-use fasteners/screws and other information regarding repair-related gaskets, seals, fluid and/or lubricants that also need to be replaced/used and claimed.

WARRANTY INFORMATION

For the MY 2016 F48 vehicles equipped with the B46O engine that are registered in California or a State that has fully adopted the State of California PZEV/SULEV regulation (CA, CT, ME, MD, MA, NJ, NY, RI, and VT):

A. The fuel tank vent (purge) valve is covered by the terms of the California Emission Warranty for 15 years/150,000 miles (whichever occurs first).

Note: Claim the qualifying repair work using the applicable defect codes and labor operations listed in AIR.

For all remaining MY 2016 F48 vehicles:

B. The fuel tank vent (purge) valve limited emission warranty has been extended to 10 years/120,000 miles (whichever occurs first).

The existing limited warranty coverage for the whole vehicle and other components has not changed.

This coverage supersedes the coverage that is provided under the BMW Certified Pre-Owned Program or any BMW Group Vehicle Service Contract that applies to the vehicle.

Should this component fail again, this component is covered by the remaining portion of the extended limited warranty coverage period.

Non-Qualifying Repairs

Non-US specification vehicles, ineligible vehicles, eligible vehicles operated and repaired outside the United States and Puerto Rico and/or the diagnosis and repair of other unrelated issues are not covered under the terms of this limited warranty extension.

Qualifying Repairs - Claim Submission

Claim this work with the defect code and labor operations provided below.

Defect Code:	1390900300	F48 B46 US tank purge valve
---	---	---
Labor Operation	Description	Labor Allowance
00 00 006	Performing vehicle test (with vehicle diagnosis system – checking faults) (Main work)	Refer to AIR
Or:		

00 00 556	Performing vehicle test (with vehicle diagnosis system – checking faults) (Plus work)	Refer to AIR
And:		
61 21 528	Support voltage of the vehicle electrical system / recharge vehicle electrical system battery	Refer to AIR
And, as necessary:		
61 00 006*	Performing vehicle diagnosis – test module	Work time (WT)
Or		
00 58 000*	Diagnosis Worktime Flat Rate (See below)	2 FRU
And:		
13 90 500	Replacing tank venting valve	Refer to AIR

If you are using a Main labor code for another repair, use the Plus code labor operation 00 00 556 instead of 00 00 006.

Refer to AIR for the corresponding flat rate unit (FRU) allowances.

Work time labor operation codes 61 00 006 and 00 58 000 are not considered Main labor operations.

*Based on which one applies to your center, please refer to **SI B01 01 20** or **B01 07 20** for claiming your diagnosis work time, job/repair work time (WT), RO/Claim WT and/or repair explanation procedures, unless otherwise required by State law.

Previous Customer-Pay Repairs – Limited Warranty Extension Reimbursement

Based on which one applies to your center, BMW of North America, LLC (BMW NA) will provide reimbursement for qualifying customer-pay repairs that were performed on an eligible vehicle **prior** to the release of this component-specific limited warranty extension (B).

Customer-pay repairs are subject to the same vehicle eligibility requirements, limitations, and exclusions that apply to the BMW New Vehicle Limited Warranty for Passenger Cars and Light Trucks.

Repairs that do not qualify for Reimbursement

Repairs performed on ineligible vehicles, eligible vehicles operated and repaired outside the United States and Puerto Rico and/or the diagnosis and repair of other unrelated issues. This exclusion also applies to repairs that were performed using (including those repairs that result from using) non-genuine BMW parts and/or used BMW passenger car or light truck parts.

Requesting Reimbursement for a Previous Repair that Qualifies

For a customer to request reimbursement for a qualifying customer-pay repair performed either by an authorized BMW center or independent repair shop located in the United States (including Puerto Rico), please have him/her submit his/her reimbursement request online at www.BMW-RP.com under the following reference:

- **B-ELWR 2019 B46 Fuel Tank Vent Valve 10Y120M**

Reimbursement Request Procedure

The online process is initiated by attaching/sending PDF files of the supporting documentation for the prior repair.

The letter also includes alternative methods to request reimbursement, either through the mail or by fax as described below:

BMW Customer Reimbursement Center
Attention: B-ELWR 2021 F22 Front Seat Belt Rollers 10Y120M
P.O. Box 54067
Hurst, Texas 76054

Fax number: 877-434-2992

Please allow 4-6 weeks for processing your request.

Should you have any questions concerning this reimbursement process, please call 1-844-857-0341.

BMW Owner/Operator Inquiries and Assistance

For all other questions, please contact the BMW's Customer Relations and Services via email at Customerrelations@bmwusa.com or via telephone at 1-800-831-1117.

Supporting Materials

[picture_as_pdf B010419_Customer Letter.pdf](#)

BMW

577 MAIN STREET
HUDSON, MA 01749
DO NOT MAIL REPAIR ORDER TO THIS ADDRESS



[Redacted]

March 2019

This **“Important Limited Warranty Information”** applies to the BMW vehicle with the Vehicle Identification Number (VIN) of [Redacted]

Dear BMW Owner/Lessee:

BMW is committed to delivering the ultimate in product satisfaction to our customers.

Towards that end, BMW is extending the limited warranty for the:

- **Fuel Tank Vent Valve**

On the above-referenced vehicle to:

- **10 years/120,000 miles as determined by your vehicle’s original in-service date.**

This “component-specific” limited warranty extension applies to defects in materials or workmanship. This coverage is subject to the same vehicle eligibility requirements, limitations, and exclusions that apply to the BMW New Vehicle Limited Warranty for Passenger Cars and Light Trucks.

This is notice of a “limited warranty extension.” This is not a notice of a Recall or Service Action.

If a repair to this component is required, please contact your nearest authorized BMW center in the United States or Puerto Rico to schedule an appointment. Your authorized BMW center will determine the vehicle’s eligibility and review the scope of repairs that are covered by this component-specific limited warranty extension.

After vehicle inspection and diagnosis, eligible repair work will be performed by the authorized BMW center in the United States (including Puerto Rico) free of charge.

Repairs performed on ineligible vehicles, eligible vehicles operated and repaired outside the United States and Puerto Rico and/or the diagnosis and repair of other unrelated issues are not covered by this limited warranty extension. This exclusion applies to repairs, including consequential, that were performed using non-genuine BMW parts and/or used passenger car or light truck parts.

The integrity of our products is essential to BMW’s success and our customers’ trust. We are determined to exceed your expectations and hope this warranty extension further enhances your ownership experience.

Sincerely,

BMW of North America, LLC

B-ELWR 2019 B46 Fuel Tank Vent Valve 10Y120M

Company
BMW of North America, LLC
BMW Group Company

Mailing Address
PO Box 1227
Westwood, NJ
07675-1227

Telephone
(800) 831-1117

E-mail
Customerrelations@
bmwusa.com

Website
bmwusa.com

Previous Customer-pay Repairs – Limited Warranty Extension Reimbursement

BMW of North America, LLC

March 2019

VIN [REDACTED]

Under this extended limited warranty, BMW of North America, LLC (“BMW NA”) will provide reimbursement for “qualifying customer-pay repairs” that were performed on an eligible vehicle **prior** to the release of this component-specific limited warranty extension.

Customer-pay repairs are subject to the applicable vehicle and coverage eligibility requirements, exclusions and limitations that apply to the BMW New Vehicle Limited Warranty for Passenger Cars and Light Trucks.

Repairs that do not Qualify for Reimbursement

Repairs performed on ineligible vehicles, eligible vehicles operated and repaired outside the United States and Puerto Rico and/or the diagnosis and repair of other unrelated issues. This exclusion applies to repairs, including consequential, that were performed using non-genuine BMW parts and/or used passenger car or light truck parts.

Requesting Reimbursement for a Previous Repair that Qualifies

If you previously had a “qualifying customer-pay repair” performed either by an authorized BMW center or independent repair shop located in the United States (including Puerto Rico), please submit your reimbursement request “online” at www.BMW-RP.com under the following reference:

Covered Component Code

B-ELWR 2019 B46 Fuel Tank Vent Valve 10Y120M

To initiate the online process, you will be asked to attach PDF files of the required documentation as outlined in the reimbursement checklist on the next page.

Alternative Method to Request Reimbursement

Alternatively, you may mail or fax your request and documentation to:

BMW Customer Reimbursement Center
Attention: B-ELWR 2019 B46 Fuel Tank Vent Valve 10Y120M
P.O. Box 561089
Dallas, TX 75356
Fax number: 877-434-2992

Please allow 4-6 weeks for processing your request.

Should you have any questions concerning this reimbursement process, please call 1-844-857-0341.

For all other questions, please contact BMW's Customer Relations and Services via email at Customerrelations@bmwusa.com or via telephone at 1-800-831-1117.

Please have your 17-character Vehicle Identification Number (VIN) available and include the VIN with all communications.

Fuel Tank Vent Valve: Limited Warranty Extension to 10 Years/120,000 Miles
Previous Customer-pay Repair Reimbursement – Documentation Checklist
BMW of North America, LLC

Reimbursement is available to the BMW Owner/Lessee who incurred the expense.

When submitting a reimbursement for a previous repair, please provide **legible copies** of the following documentation and include your VIN, name, address and your preferred contact telephone number(s):

Repair Order (RO) or Invoice

This document should include the following information:

- Customer name and address
- Vehicle Identification Number (“VIN”)
- The date of repair
- The mileage when the repair was performed
- Itemized breakdown of the labor charges for all repairs* including diagnosis
- Itemized breakdown of the parts, including any miscellaneous items, billed for all repairs*

*For repair orders containing multiple repair line items, only the specific line item expenses that relate to the component that is covered by this extended limited warranty will be considered for reimbursement.

Proof of Payment

Please provide a copy of at least **one** of the following items as valid proof of payment:

- Repair order (RO)/invoice stamped and dated as “PAID”
- Copy of a cancelled check
- Copy of a signed credit/debit card receipt
- Copy of a credit/debit card statement

Determining if an eligible vehicle’s repair qualifies for reimbursement:

Please use the following questions to review your repair order documentation prior to submitting a reimbursement request:

1. Why was the vehicle brought into the repair facility?
2. What was the repair facility’s diagnosis?
3. What did the repair facility do to correct the concern and does it qualify?