

CAMPAIGN LAUNCH STATUS

L462 CAMPAIGNS



SERVICE ACTION N564 18-19MY L462 WINDSHIELD WATER LEAKS	
AFFECTED MODELS	18-19 MY Discovery
VOLUME AFFECTED	13,452 USA 709 CAN
REPAIR	Following procedures similar to those in prior campaigns, N292 & N221, affected vehicles require a water leak test and a test with compressed air. If required, a replacement windshield is to be installed if the tests fail.
REPAIR TIME	Between 0.4 and 2.6 hrs plus drive in/out
TARGET CAMPAIGN LAUNCH	August 9 th 2021
Notes	Extends prior service actions to include additional model years

N591 OWNER NOTIFIED SERVICE ACTION - L462 INCORRECT 20" WHEELS INSTALLED	
AFFECTED MODELS	21-22MY Discovery with 20" wheels
VOLUME AFFECTED	269 USA 2 CAN
REPAIR	Some customers have paid for the optional Aero Viper style 5011 wheel but received the standard Discus style 5122 wheel and some customers have received the optional Aero Viper style wheel at no additional cost. Customers will be notified by mail and given the option of having the wheels replaced back to the ordered spec or being reimbursed if they ordered the optional Viper style wheel but choose to keep the Discus style.
REPAIR TIME	Up to 1.5 hrs + drive in/out, if wheels are replaced.
TARGET CAMPAIGN LAUNCH	8 th August, 2021
Notes	