



LCI Slide Room Actuator

Description

On certain 2021 Heartland Fuel, Torque, Sundance, Pioneer, Prowler travel trailers, 2021 Cruiser MPG, Twilight, Shadow Cruiser travel Trailers, and 2021 Heartland Cyclone, Gravity, Fuel, Torque, Big Horn Traveler, Milestone, Elkridge fifth Wheels, an assembly error by our external vendor could cause the slide room actuator to not allow the slide room to retract.

VIN Range Effected

5RXPB3322M1467103 - 5SFCB3129ME471143 *Non sequential*****

Inspection & Repair

Please see attached repair instructions:

Contact LCI for technical questions:

(574) 537-8900

customerservice@lci1.com

Lippert.com

Warranty

Once completed file warranty claim at Heartland or Cruiser Service Departments using warranty code 98.01.24 for .6 hours for inspection and 2.2 hours for replacement.

Please refer all questions and authorization requests to Heartland Dealer Services Department 877-262-8032 or Cruiser Service Department 260-562-3500