



Bulletin No.: PIC6440  
Published date: 07/1/2021

# Preliminary Information

## PIC6440 Rear HVAC Blower Controls Change Front Blower Speed

Models

| Brand:   | Model: | Model Years: | VIN: |     | Engine: | Transmissions: |
|----------|--------|--------------|------|-----|---------|----------------|
|          |        |              | from | to  |         |                |
| Cadillac | CT6    | 2018 - 2020  | All  | All | All     | All            |

|                            |   |
|----------------------------|---|
| Involved Region or Country | North America   |
| Additional Options (RPO)   | C24 - QUAD-ZONE CLIMATE CONTROL AIR   |
| Condition                  | When adjusting the rear HVAC fan speed, the front fan speed will also change. |
| Cause                      | Calibration change  |

**Correction:**

None, a calibration change was made starting with the 2018 model year. This is normal operation, do not replace any parts or attempt to repair.

Warranty Information

Version History

|          |                          |
|----------|--------------------------|
| Version  | 1                        |
| Modified | 07/01/2021 - Created on. |



GENERAL MOTORS