

Subject

Hydrogen Tank Cover Appearance Condition

Market

USA

Service Category

Engine/Hybrid System

Section

Fuel System

Applicability

2016-2020 MIRAI

APPLICABLE VEHICLES

2016-2020

Mirai

CONDITION


During vehicle inspections, when the vehicle under covers are removed, debris is found on the undercover near the end of the hydrogen tank. Upon closer inspection the debris is found to be coming from the end protector of the tank.

RECOMMENDATIONS

During vehicle use heat and ultraviolet light can cause degradation of the tank protector causing the foam to come off.

This protector is added by the supplier to protect the tank during the production process, this does not negatively affect the tank and is only an appearance concern.

It is recommended to clean the undercovers before reinstalling. No repairs are recommended.



1. Degraded foam

2. Debris on undercover

LINK REFERENCES

This Tech Tip does not contain any link references