

Fasteners – Temporary Deviation

Temporary Deviation

TBB is dealing with multiple Fastener supply shortages; you may notice a change of fasteners in some areas of our products. Please rest assured that engineering has developed, validated and approved substitutions to ensure that our products remain compliant.

This is only a temporary deviation until such time as the supply of fasteners recovers; it will impact potentially all of our products manufactured in High Point, NC.

Features and Benefits

Fasteners substitutions do not alter the durability or performance of our buses; it allows us to continue to manufacture units despite the cosmetic differences. Please be aware that in some instances, you may identify multiple deviations in the same areas.

<input checked="" type="checkbox"/> Saf-T-Liner C2	<input checked="" type="checkbox"/> Saf-T-Liner HDX	<input checked="" type="checkbox"/> Saf-T-Liner EFX
<input checked="" type="checkbox"/> Minotour DRW	<input checked="" type="checkbox"/> Minotour SRW	<input type="checkbox"/> Minotrek

Some more visible areas where substitutions are/were used are:

C2 Seat Rail



SUBSTITUTED BOLTS FOR RIVETS

EFX Front Wall



SUBSTITUTED SCREWS & NUTS FOR RIVETS WITH THE EXCEPTION OF CIRCLED AREAS

HDX Front Wall



SUBSTITUTED SCREWS & NUTS FOR RIVETS WITH THE EXCEPTION OF CIRCLED AREAS

Examples of Areas Impacted

