




RVC BRIDGE; INVERTER LOCATIONS

Bulletin Type:	INC	Publication Date:	October 2021
Bulletin #(s):	21-040	Make(s):	Jayco & Entegra Coach
Model Year(s):	2017-2022	Model(s):	EMBARK, REATTA, REATTA XL, ASPIRE, ANTHEM, CORNERSTONE

Incident:	Locating RVC Bridge.
Affected Units:	2017-2022 Jayco Embark & 2017-2022 Entegra Reatta, Reatta XL, Aspire, Anthem, Cornerstone

VISUAL INSTRUCTIONS FOR LOCATING THE RVC BRIDGE


1. MY2017 RVC Bridge is located behind the black plastic panel in the overhead cabinet above the entrance door. An example of the RVC Bridge is shown in Fig 1. Please refer to step 6 for visual instructions.
2. MY2018 RVC Bridge is located in the third or fourth cargo door, passenger side, beside the batteries, and behind the carpeted lid which is Velcroed to the front of the box. An example of the RVC Bridge is shown in Fig 1. Please refer to step 5 for visual instructions.
3. MY2019 through MY2022 RVC Bridge is located on the cargo ceiling above and near the inverter between the main chassis frame rails. An example of the RVC Bridge is shown in Fig 1.
 - a. Enter the third or fourth passenger side cargo door, and the RVC Bridge is located overhead between the main chassis frame rails
 - b. Please refer to step 4 for visual instructions.



RVC Bridge:


4. MY2019-2022

- a. Fig 2 shows the RVC Bridge fastened to the ceiling of the cargo area near the inverter.




5. MY2018

- a. Access by entering the third or fourth cargo door. Velcro panel is facing forward (Photo "A").
- b. Shows the RVC Bridge in the compartment under a Velcro lid, bottom right corner of the electrical compartment (Photo "B").



6. MY2017

- a. Bridge is located in behind the black panel shown in Fig 3 & Fig 4 in the overhead cabinet above the entrance door.



Jayco's sole obligation under our limited warranty is to repair or replace defective materials and/or workmanship deemed our responsibility as determined by Jayco in our sole discretion. Jayco reserves the right to use new and/or remanufactured parts or materials of similar quality to complete any work, and to make parts and/or design changes as appropriate without notice to anyone. Jayco designs and/or materials changes are done without obligation to incorporate such changes in previously manufactured product. Jayco makes every reasonable effort to ensure field remedies will not adversely affect performance and/or safety of the unit. This field remedy is not intended to extend to future performance of this RV, or any of its materials, components or parts beyond the standard warranty period. The RV owner's obligation to notify Jayco, or one of its independent, authorized dealers, of a claimed defect does not modify any obligation placed on the RV owner to contact Jayco directly when attempting to pursue remedies under state or federal law. Jan. 2019.

903 South Main Street • P.O. Box 460 • Middlebury, IN 46540