



SERVICE BULLETIN

Classification: BT21-009	Reference: NTB21-082	Date: September 9, 2021
-----------------------------	-------------------------	----------------------------

REAR KICKING PLATE PART CHANGE

APPLIED VEHICLES: 2022 Pathfinder (R53)

SERVICE INFORMATION

The rear kicking plates have been updated to delete a rear clip. If a rear kicking plate is being replaced, use the parts listed in the **PARTS INFORMATION** on page 2.

IMPORTANT: When replacing a rear kicking plate with an updated part, early production vehicles must have the hole for the deleted clip covered with a body patch (Figure 1), to prevent water intrusion.




Figure 1

Nissan Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. **NOTE:** If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Nissan dealer to determine if this applies to your vehicle.

PARTS INFORMATION

DESCRIPTION	PART NUMBER	QUANTITY
PLATE - KICKING, REAR RH	769B6-6TA1A	1
PLATE - KICKING, REAR LH	769B6-6TA1A	1
COVER - HOLE (Body Patch)	64891-W5000	(1)

(1) One required per side, as needed.

AMENDMENT HISTORY

PUBLISHED DATE	REFERENCE	DESCRIPTION
September 9, 2021	NTB21-082	Original bulletin published