

[Translate](#)



SPYDER RT 2021 Storage Panel Rework Needed - 139442

Summary:

These 2 rear storage panels will need some minor rework if replaced on MY21 RT.


Type:

General

TST Detail:

Problem:

If ever you have to replace a rear saddlebag 708303846 or 708303847, some minor rework will be necessary. Two holes are missing for the retaining clamps.




Solution:

The templates to rework the rear storage box according to the production vehicle are attached below.

Print to scale (1:1), cut the outlines, and align details on the part to locate the area to modify.

Inspection Procedure:



[Translate](#)

Print 1 sheet of paper

Destination: Canon TS9100 series

Pages: All

Copies: 1

Color: Color

More settings ^

Paper size: Letter

Pages per sheet: 1

Quality: 300 dpi

Scale: Default

Two-sided: Print on both sides

Print using system dialog_ (Ctrl+Shift+P)

Print Cancel

Warranty:

If the vehicle is still under normal warranty then you can file a repair under claim type 01, job code 09-294 and add 0.3h in the actual time, for one side, for the rework.

Attachment: 708303847 - TEMPLATES_F1_1 (1).pdf

First Published By: Eric Fauteux on 2021-10-27
Last Modified By: Eric Fauteux on 2021-10-28