

**** TECHNICAL INFORMATION NOTICE ****


DATE: October 25, 2021
TO: Mitsubishi Motors US & Puerto Rico Dealer Service and Parts Managers
RE: Loose Leather Trim on Center Console sides
TIN NO. TIN-21-52A-002

.....

AFFECTED VEHICLES: 2022 Outlander

PURPOSE

If you have a 2022 Outlander with the complaint of leather trim coming loose on the sides of the center console, please replace the affected finisher with a new part. In the event of a backorder supply concern you can instead have part number 8011C440XA or 8011C440XB repaired. The leather can be bonded back to the trim panel with the addition of staples in several areas by an upholsterer.



Warranty Claim

File a claim for the sublet repair and as always, please adhere to the Policy and Procedures manual when submitting.