

TECHNICAL NEWS 219



Notice Information

Ref	19441
Posted Date:	
Posted To:	General Manager / Business Owner, Technician, Parts / Accessories Coordinator, Sales Executive, Clothing Sales, Sales Manager, Aftersales Manager, Service Leader / Advisor, Accounts / Admin, Marketing Executive
Subject:	Service/Technical

TOL NOTICE (US&CA) – September 9, 2021

TOL Ref. # 19441-SVC

TECHNICAL NEWS 219

Technical News 219 is now available for download on the Triumph Technical News library located at **Triumph Online > Service/Technical > Technical News** or you can consult the attached [Technical News 219](#) PDF. Please ensure your workshops and all relevant staff are aware of the contents and any absent staff are informed upon their return. Please also update your workshop service manuals, procedures and have a printed copy available where appropriate.

Technical News 219		
Item	Subject	Model Affected
219.1	Engine Oil and Filter Change	Speed Triple 1200 RS
219.2	Fuel Hose Disconnection	Rocket 3 Family
219.3	Chain Rubbing Strip	Tiger 850 Sport and Tiger 900 Family
219.4	Triumph Diagnostic Tool – Suspension Diagnostics – Rear Preload Motor Function Tests	Tiger 900 GT Pro
219.5	Appendix A – Rear Suspension Unit – Rear Preload Motor Calibration	Tiger 900 GT Pro
219.6	Appendix B – Test Rear Preload Motor	Tiger 900 GT Pro

If you have any additional questions, please contact Triumph Customer Support at (888) 284-6288.

