

Technical Service Bulletin

44 Collapsible spare wheel does not inflate fully using the compressor from the vehicle tool kit

44 21 84 2065160/1 November 19, 2021.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
All	2010 - 2023	All	Not Applicable

Condition

Customer states:

• The temporary/collapsible spare wheel does not inflate fully when it is filled using the compressor from the breakdown set. The pressure specified on the collapsible spare wheel is not reached using the compressor.

Technical Background

The collapsible spare wheel is in suitable condition to use on the vehicle when the tire tread is aligned horizontally with the hub. When this is the case, the side wall of the collapsible spare wheel may not be aligned symmetrically with the rim, giving the impression that the tire has not inflated fully. The compressor reaches a pressure of 3.5 bar after running for a certain period; this is sufficient for using the tire (Figures 1 -2).



Figure 1. Correct tire position – tread aligned symmetrically with the rim/hub.




Figure 2. Tire assembly; Incorrect and correct positions shown.

Production Solution

Not applicable.

© 2021 Audi of America, Inc.

Page 1 of 2

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.



Technical Service Bulletin

Service

Not applicable.

Warranty

This TSB is informational only and not applicable to any Audi Warranty.

Additional Information

All part and service references provided in this TSB (2065160) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2021 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.

© 2021 Audi of America, Inc.

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.