

Service Alert

Mazda North American Operations
Irvine, CA 92618-2922



Subject:

**DTC C0061:94 DIAGNOSTICS MISSING IN THE WORKSHOP
MANUAL ON MGSS**

Service Alert No.: SA-055/21

Last Issued : 11/17/2021

APPLICABLE MODEL(S)/VINS

2019-2021 Mazda3

2020-2021 CX-30

DESCRIPTION

Due to a supplier issue, DTC C0061:94 is displayed instead of C0061:96 for Mazda3 and CX-30. Therefore, use the C0061:96 diagnostics on MGSS when DTC C0061:94 is stored.

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.