

# TECHNICAL TOPICS BODY/CHASSIS



<p>Front Suspension Knocking Noise</p>	<p>17 - 21MY F-PACE, 18 - 21MY RR Velar</p>
<p><u>Customer Voice:</u></p> <ul style="list-style-type: none"> <li>- A customer may report a noise from the front suspension when driving at low speeds with steering input applied.</li> </ul> <p><u>Technical Description:</u></p> <ul style="list-style-type: none"> <li>- Front suspension upper control arms are being replaced to address a suspension knock type noise concern, but root cause is not understood.</li> </ul> <p><u>Status:</u></p> <ul style="list-style-type: none"> <li>- Engineering is currently investigating this concern.</li> <li>- SSM 75581 (Land Rover) and 75582 (Jaguar) have been published to support the investigation of this concern, requesting information to be provided in an EPQR submission.</li> <li>- Please refer to these SSM should a customer express a concern, retain any replaced parts and submit an EPQR with the requested data to support the investigation. Thank you for your support.</li> </ul>	



PRINTED COPIES ARE UNCONTROLLED