* * TECHNICAL INFORMATION NOTICE * *

DATE: November 10, 2021

TO: Mitsubishi Motors US & Puerto Rico Dealer Service and Parts Managers

RE: Error in Diagnostic Procedure for P0780 CVT Shift Control System

TIN NO. TIN-21-23-001

AFFECTED VEHICLES: 2022 Outlander

PURPOSE

When diagnosing a CVT shifter concern related to the shift actuator or for code P0780 the last step indicates incorrectly that a possible cause may be the shift actuator and that if confirmed the transaxle should be replaced. If diagnostics lead to a shift actuator **DO NOT REPLACE THE CVT TRANSAXLE**. The shift actuator and inhibitor switch are both available as separate parts and should be replaced independently of the transaxle.

Shift Actuator	2615A043
Inhibitor Switch	8617B127

TRANSAXLE & TRANSMISSION							
P0780-00 SHIFT ERROR							
DTC D	escrip	tion					
TC DE	TECTI	ON LOGIC					
DTG	D	M.U.TIII SE screen terms (Trouble diagnosis content)	DTC detection condition				
P0780				Diagnosis condition Signal	Ignition switch: ON		
	Shift error (Shift Error)		1	Threshold	Target range and actual range (range of transmission range switch) do not match.		
				Diagnosis delay time	1.3 seconds		
				Diagnosis condition	Ignition switch: ON		
		Shift error	2	Signal	-		
		(Shift Error)		Threshold	Target range and redundant range do not match		
				Diagnosis delay time	0.38 seconds		
				Diagnosis condition	Ignition switch: ON		
				Signal	-		
			3	Threshold	Actual range (range of transmission range switch) and redundant range do not match		
			Diagnosis delay time	0.38 seconds			

Page 1 of 2 (5144)

Diagnosis Procedure	Do not replace transaxle for a	
1. REPLACE TRANSAXLE ASSEMBLY	inhibitor switch or shift actuator	
Replace the transaxle assembly due to malfunction in the shift actuator. Refer to TRANSAXLE ASSEMBLY . >>>	failure. Both parts are available separately.	
WARK ENG		-

Note: Replacements of the transaxle assembly where replacement of just the inhibitor switch or shift actuator would have repaired the vehicle, are subject to claim denial. Please follow all Warranty Policy and Procedure steps when submitting claims.