

TECHNICAL BULLETIN 220: ENCAPSULATED FIXINGS



Notice Information

Ref 19845

Posted Date:

Posted To: General Manager / Business Owner, Technician, Parts / Accessories Coordinator, Sales Executive, Clothing Sales, Sales Manager, Aftersales Manager, Service Leader / Advisor, Accounts / Admin, Marketing Executive

Subject: Service/Technical

TOL NOTICE (US&CA) – October 22, 2021

TOL Ref. # 19845-SVC

TECHNICAL BULLETIN 220: ENCAPSULATED FIXINGS

Triumph has released [Technical Bulletin 220](#) including 5 subjects across a range of models.

Technical Bulletin 220			
Bulletin #	Subject	Models Affected	Markets
220.1	Encapsulated Fixings	All Models	All Markets
220.2	Cruise Control Switch Check Process and Clearing DTC P1575	All models fitted with cruise control	All Markets
220.3	Clutch Switch	See Bulletin for full list	All Markets
220.4	Gear Change Selector Mechanism Parts Kit	Street Cup, Street Twin, Bonneville T100 models from VIN 759204, Street Scrambler, Thruxton 1200, Thruxton 1200R, Bonneville T120 models, Bonneville Bobber, Bonneville Speedmaster from VIN 739143 and Bonneville Bobber Black	All Markets
220.5	TriTun Document Portal to be Replaced by a New System	All Models	All Markets

Some affected motorcycles listed in the VIN range will have been modified and repaired by Triumph prior to their release from the factory. Unmodified motorcycles can be identified by checking the 'VIN Enquiry' on www.triumphonline.net. **Motorcycles in the affected VIN range must be modified prior to delivery to the customer, or at the next dealership visit.**

Consult **Triumph Online (TOL) / Technical Bulletin Page** (Bulletin #220) or the attached [Technical Bulletin 220](#) PDF for additional information.

Reminder: Use the **"VIN Enquiry"** function within TOL (found under the **Service / Technical** drop-down menu) to search for any outstanding bulletins or recalls whenever a new motorcycle arrives, or a Triumph owner visits your dealership.

If you have any additional questions, please contact Triumph Customer Support at (888) 284-6288.