VOLVO

Service and Parts Business

Technical Journal

TITLE: SiriusXM Radio missing from Google/Android Infotainment **REF NO: ISSUING DEPARTMENT:** CAR MARKET: TJ 36065.1.1 **Technical Service United States and Canada** PARTNER: **ISSUE DATE:** STATUS DATE: 3 US 7510 Volvo Car USA 2021-10-08 2021-10-13 FUNC DESC: FUNC GROUP: Media, navigation and 3900 Page 1 of 2 communication

"Right first time in Time"

Rows beginning with * are modified

Note! If using a printed copy of this Technical Journal, first check for the latest online version.

DESCRIPTION:

If a customer complains that the SiriusXM satellite radio media source is missing from the vehicle. See instructions under Service.

IHU = Infotainment Head Unit PDS = Pre-Delivery Service

CSC Customer Symptom Codes

Code	Description
2P	Satellite radio/Does not work

DTC Diagnostic Trouble Codes

Vehicle Type

Туре	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
236							2022-2022		-	202120-202139
238							2022-2022		-	202120-202139
246							2022-2022		-	202120-202139
536	ED	E400V6					2021-2022		-	202037-202139

Produced in the USA and available as an electronic document. Hard copy documents are printed in USA on recycled paper containing a minimum of 50% wastepaper and 10% post-consumer waste. © 2021 VOLVO CAR USA, LLC

Technical Journal 36065.1.1

SERVICE:

To add the SiriusXM app to the vehicle, install the latest IHU software by following guidelines in TJ 31543. The software is included in the latest *Total Upgrade*, *Service 2.0*, and *PDS Upgrade* packages.

Once the software is loaded to the vehicle, the radio will be active and the customer's 3-month trial subscription period will begin.

For un-sold vehicles that receive *PDS Upgrade* software (ex. demonstration units), the radio will be activated and functional after the software is downloaded, but the 3-month trial period will not begin until the vehicle sale is completed and recorded in the Retail Delivery Registry.

Warranty claim information

To get a warranty claim accepted for a job described in this TJ, please use following data: VST OP number: 36004-2 and CSC 2P.

VST Operation Number

VST Operation Number	Description
36004-2	Software control module downloading

VEHICLE REPORT: Not required