

GPOP - Issue Review System

Part Number: 68364385A\$

Part Description: LATCH, Liftgate

Issue Description: If the customer experiences an intermittent liftgate ajar light, please call FCA Redacted Content before replacing the latch. If no response in 15 minutes, proceed with repair.

~
Contact us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. Please include the Part Number(s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.
~