

GPOP - Issue Review System

Part Number: 68462119A\$

Part Description: COMPRESSOR ASSEMBLY, Air Suspension, Module

Issue Description: ASCM replacement is rarely necessary. If the DTC is stored and able to be cleared, component replacement is not necessary.

Please follow the service procedures to attempt to clear any active fault(s) which includes module hard reset, full CAN power down/sleep, or DTC clear in WiTech.

Please contact FCA Redacted Content prior to any ASCM replacement at FCA Redacted Content

If no response within 15 minutes, please proceed with repair.

Any new module requires a flash following installation.

~_____
Contact us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. Please include the Part Number(s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.