

GPOP - Issue Review System

Part Number: 5ZK43GTWA\$, 5ZK42GTWA\$, 5ZK45GTWA\$, 5ZK44GTWA\$, 5ZK47GTWA\$, 5ZK46GTWA\$, 5ZK49GTWA\$, 5ZK48GTWA\$, 5ZK43GW7A\$, 5ZK42GW7A\$, 5ZK45GW7A\$, 5ZK44GW7A\$, 5ZK47GW7A\$, 5ZK46GW7A\$, 5ZK49GW7A\$, 5ZK48GW7A\$, 5ZK43JSCA\$, 5ZK42JSCA\$, 5ZK45JSCA\$, 5ZK44JSCA\$, 5ZK47JSCA\$, 5ZK46JSCA\$, 5ZK49JSCA\$, 5ZK48JSCA\$, 5ZK43JWDA\$, 5ZK42JWDA\$, 5ZK45JWDA\$, 5ZK44JWDA\$, 5ZK47JWDA\$, 5ZK46JWDA\$, 5ZK49JWDA\$, 5ZK48JWDA\$, 68276505A\$, 68276504A\$, 5ZK43KARA\$, 5ZK42KARA\$, 5ZK45KARA\$, 5ZK44KARA\$, 5ZK47KARA\$, 5ZK46KARA\$, 5ZK49KARA\$, 5ZK48KARA\$, 68276507A\$, 68276506A\$, 5ZK43KCLA\$, 5ZK42KCLA\$, 5ZK45KCLA\$, 5ZK44KCLA\$, 5ZK47KCLA\$, 5ZK46KCLA\$, 5ZK49KCLA\$, 5ZK48KCLA\$, 68276509A\$, 68276508A\$, 5ZK43KGZA\$, 5ZK42KGZA\$, 5ZK45KGZA\$, 5ZK44KGZA\$, 5ZK47KGZA\$, 5ZK46KGZA\$, 5ZK49KGZA\$, 5ZK48KGZA\$, 68276511A\$, 68276510A\$, 5ZK43KXJA\$, 5ZK42KXJA\$, 5ZK45KXJA\$, 5ZK44KXJA\$, 5ZK47KXJA\$, 5ZK46KXJA\$, 5ZK49KXJA\$, 5ZK48KXJA\$, 5ZK43LAUA\$, 5ZK42LAUA\$, 5ZK45LAUA\$, 5ZK44LAUA\$, 5ZK47LAUA\$, 5ZK46LAUA\$, 5ZK49LAUA\$, 5ZK48LAUA\$, 5ZK43NRVA\$, 5ZK42NRVA\$, 5ZK45NRVA\$, 5ZK44NRVA\$, 5ZK47NRVA\$, 5ZK46NRVA\$, 5ZK49NRVA\$, 5ZK48NRVA\$, 5ZK43PR4A\$, 5ZK42PR4A\$, 5ZK45PR4A\$, 5ZK44PR4A\$, 5ZK47PR4A\$, 5ZK46PR4A\$, 5ZK49PR4A\$, 5ZK48PR4A\$, 5ZK43RPXA\$, 5ZK42RPXA\$, 5ZK45RPXA\$, 5ZK44RPXA\$, 5ZK47RPXA\$, 5ZK46RPXA\$, 5ZK49RPXA\$, 5ZK48RPXA\$, 68343432A\$, 68343434A\$, 68343436A\$, 6LC10GTWA\$, 6LC12GTWA\$, 6LC14GTWA\$, 6LC16GTWA\$, 68343438A\$, 6LC10GW7A\$, 6LC12GW7A\$, 6LC14GW7A\$, 6LC16GW7A\$, 6LC10JSCA\$, 6LC12JSCA\$, 6LC14JSCA\$, 6LC16JSCA\$, 6LC10JWDA\$, 6LC12JWDA\$, 6LC14JWDA\$, 6LC16JWDA\$, 6LC10KARA\$, 6LC12KARA\$, 6LC14KARA\$, 6LC16KARA\$, 68276477A\$, 68276476A\$, 6LC10KCLA\$, 6LC12KCLA\$, 6LC14KCLA\$, 6LC16KCLA\$, 68276479A\$, 68276478A\$, 6LC10KGZA\$, 6LC12KGZA\$, 6LC14KGZA\$, 6LC16KGZA\$, 6LC10KXJA\$, 6LC12KXJA\$, 6LC14KXJA\$, 6LC16KXJA\$, 6LC10LAUA\$, 6LC12LAUA\$, 6LC14LAUA\$, 6LC16LAUA\$, 6LC10NRVA\$, 6LC12NRVA\$, 6LC14NRVA\$, 6LC16NRVA\$, 6LC10PR4A\$, 6LC12PR4A\$, 6LC14PR4A\$, 6LC16PR4A\$, 6LC10RPXA\$, 6LC12RPXA\$, 6LC14RPXA\$, 6LC16RPXA\$

Part Description: MIRROR, Outside Rearview - w/ Memory

Issue Description: If the outside rearview mirror is being replaced for concern of "Mirrors tilt in reverse but do not return to the pre-set position after shifting out of reverse gear or continue to tilt downwards even after shifting out of reverse gear". Do not replace the mirror as it will not correct the issue. A software update has been released. Please review TSB 08-116-21 for the repair procedure which would involve reprogramming the DDM and PDM with the latest available software.

~ ~

Contact us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. Please include the Part Number(s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.

