



**NUMBER:** 08-066-21

**GROUP:** 08 - Electrical

**DATE:** April 27, 2021

*This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.*

**This Technical Service Bulletin (TSB) has also been released as a Rapid Response Transmittal (RRT) 21-044, date of issue April 27, 2021. All applicable Sold and Un-Sold RRT VINs have been loaded. To verify this RRT service action is applicable to the vehicle, use VIP or perform a VIN search in DealerCONNECT/Service Library. All repairs are reimbursable within the provisions of warranty. This RRT will expire 18 months after the date of issue.**

**SUBJECT:**

Installing the Battery Positive Protection Cover (Missing)

**OVERVIEW:**

This bulletin involves installing the missing positive battery post protective cover.

**MODELS:**

2021 (B1) Jeep Renegade

**NOTE: This bulletin applies to vehicles within the following markets/countries: LATAM.**

**NOTE: This bulletin applies to vehicles built on or after February 01, 2021 (MDH 0201XX) on or before March 13, 2021 (MDH 0313XX).**

**SYMPTOM/CONDITION:**

The positive battery cable protective cover is missing.

**DIAGNOSIS:**

If a customer's VIN is listed in VIP or your RRT VIN list, perform the repair. **This RRT only applies to vehicles on the RRT VIN list.**

**PARTS REQUIRED:**

Qty.	Part No.	Description
1	68115947AA LATAM 51831494 MOPAR	Cover, Battery Positive Protective

**REPAIR PROCEDURE:**

1. Install the protective cover for the positive post on the battery, by pushing the tabs into the locating holes in the battery (Fig. 1) .



**Fig. 1**  
**Positive Battery Protective Cover**

**POLICY:**

Reimbursable within the provisions of the warranty.

**TIME ALLOWANCE:**

Labor Operation No:	Description	Skill Category	Amount
08-08-01-9B	Protective Cover on Positive Battery Post - Install (0 - Introduction)	6 - Electrical and Body Systems	0.1 Hrs.

**FAILURE CODE:**

ZZ	Service Action
----	----------------