

## **GPOP - Issue Review System**

**Part Number:** 6WN54LT5A\$, 6WN54TU6A\$, 6WN55BD3A\$, 6WN55HL1A\$

**Part Description:** INSTRUMENT PANEL, Base Panel (Top Pad, Leather)

**Issue Description:** If you are replacing a leather instrument panel top pad for any leather defects (bubbling, delamination, wrinkling, etc.), please contact FCA Redacted Content.

If no response in 15 minutes, proceed with repair.

Please send pictures of the leather defect to FCA Redacted Content.

~ \_\_\_\_\_ ~  
Contact us at [CAGRIS@Chrysler.com](mailto:CAGRIS@Chrysler.com) for feedback related ONLY to this GPOP Tech Tip. Please include the Part Number(s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.