



## STAR ONLINE PUBLICATION




**Case Number:** S2108000180

**Release Date:** July 2021

**Symptom/Vehicle Issue:** Air Bag Warning Lamp On Or Wipers Stay On All The Time

**Customer Complaint/Technician Observation:** Owner complains the wipers are on all the time and the air bag lap is illuminated. Technician observed the vehicle may be setting some of the associated DTC's, **B0001-2B Driver Frontal Squib 1 Control-Wires Shorted Together, B0002-2B Driver Frontal Squib 2 Control-Wires Shorted Together, B0003-2B (Driver Frontal Squib 3 Control-Wires Shorted Together, U0212 Lost Communication With Steering Column Control Module, U121E Lost Communication with Cruise Control Switch, U112D Lost Communication with EVIC Steering Wheel Switches.**

**Repair Procedure:** Inspect the driver air bag squib harness connections as shown and secure any and all CPA connector locks if air bag DTC's are present. For vehicles setting loss of communications with the SCCM DTC's, secure the involved SCCM connector(s) to complete, no parts required, test the operation.



This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

**Contact STAR Center, or your Technical Assistance Center Via TechCONNECT or eCONTACT ticket if no solution is found**