

GPOP - Issue Review System

Part Number: 68411418A\$, 68411419A\$

Part Description: BRACKET, Front Bumper

Issue Description: Whenever the 2021MY Dodge Durango fascia bracket is replaced, Please confirm the presence of three 3 inch square foam blocks inside the fascia above lower grille. If you have any questions or no foam pieces are present, please FCA Redacted Content

Please email pictures and VIN # to FCA Redacted Content

~_____~

Contact Us at CAGRIS@Stellantis.com for feedback related ONLY to this GPOP Tech Tip. DO NOT email regarding repair procedures unrelated to this Tech Tip or part order inquires. Please include the Part Number (s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.