

GPOP - Issue Review System

Part Number: 6YJ312X7A\$, 6YJ324X7A\$, 6YJ325X7A\$, 6YJ332X7A\$, 6YJ344X7A\$,
6YJ345X7A\$, 6MJ382X7A\$, 6MJ394X7A\$, 6MJ395X7A\$, 6NS232X7A\$,
6NS244X7A\$, 6NS245X7A\$, 6KU841X7A\$, 6KU851X7A\$, 6KU861A6A\$,
6KU861X7A\$, 6KU862X7A\$, 6ZD791X7A\$, 6ZD801X7A\$, 6ZD811A6A\$,
6ZD811X7A\$, 6ZD812X7A\$, 7AS59DX9A\$, 7AS59TX7A\$, 6WJ52DX9A\$,
6VZ23DX9A\$, 6VZ22DX9A\$

Part Description: Driver Airbag with Module Damper

Issue Description: Model year 2022 Jeep Compass, Jeep Grand Cherokee L, Jeep Grand Cherokee, Jeep Wagoneer and Jeep Grand Wagoneer all utilize next generation Driver Airbag (DAB) and steering wheel systems. These new systems use the mass of the DAB as a damper to reduce steering wheel vibration experienced by the driver. The DAB is still securely attached to the steering wheel but now has specially tuned isolators to allow a small amount of damping movement of the DAB. A driver of these vehicles may, at times, notice this movement or vibration of the DAB within the steering wheel compared to past systems; however, this is normal and an expected function of the damping system.

~
Contact us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. Please include the Part Number(s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.