

On-car analysis list from January 31st, 2022
please contact VW Helpline before attempting repair

	Models	MY	Engine	Transmission	Topic	Customer Complaint
Powertrain	Atlas, Atlas Cross Sport	21-22	All	All	Heat Shield Rattle	Customer states rattle noise from the underbody heat shields
Chassis	Atlas, Atlas Cross Sport	21	All	All	Front Suspension Noise	Customer states noise from front suspension (Untouched vehicles) Must be after VIN break MC537933 (Atlas) or MC201092 (Atlas Cross Sport)
Electric	Tiguan	21-22	All	All	Blower stays on Faults B10AE31, B10AE04	Customer states blower stays on (Must have faults code B10AE31 and/or B10AE04 and Corrosion in high pressure sensor connector)
Other	Jetta, Golf, Beetle, SportWagen	09-14	2.0 (CJAA and CBEA)	All	TDI Inspection	Any TDI Gen I TDI within the vehicle/MY range. Topic is for information gathering only Web tickets only (\$40 technician gift card for vehicles reported) (Complete worksheet Gen 1 TDI No DPF faults VIN4PIN when creating WEB ticket) (Cannot have any DPF faults/DPF related issues)