



Technical Service Bulletin

91 Driver Assist Systems sporadically inop (DTC B200FF0 / B2F0100)
91 22 65 2065726/1 January 8, 2022.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A3 and S3	2022	All	Not Applicable

Condition

Customer states:

The driver assist systems are sporadically unavailable

Multiple messages stating the above can be displayed on the instrument cluster, for example:

- Adaptive cruise assist: currently unavailable. See owner's manual.
- Lane assist: currently unavailable. See owner's manual.
- Audi pre sense: currently restricted. See owner's manual

After an ignition cycle, the instrument cluster messages disappear and all systems return to full functionality.

Workshop findings:

The following DTC is stored in the front camera for driver assist systems, R242 (address word 00A5):

DTC B200FF0: Internal malfunction (symptom code: **1124116**)

and/or

DTC B2F0100: Development code 1 (symptom code **1124198**)

Technical Background

A software malfunction may cause the DTCs to be entered in the front camera for driver assistance systems.

Production Solution

This bulletin will be updated when more information is available. A solution is currently under development.

Service



Technical Service Bulletin

1. Explain to the customer that a solution is forthcoming for the 4th quarter of 2022 and that no repairs are necessary at this point. Do not replace any components for this condition since this will not resolve the customer's concern.
2. Through the Pending Service Solutions (PSS) link in Access Audi under *Related Links >> Service*, or through the Technical Assistance page in Elsa, create a PSS record in the application.

Warranty

This TSB is informational only and not applicable to any Audi Warranty.

Required Parts and Tools

Additional Information

All part and service references provided in this TSB (2065726) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2022 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.